



This exploded view diagram illustrates the assembly of a mechanical component. The parts are identified by numbered callouts and labels:

- 1**: A long, tapered shaft or pin with a threaded section at one end.
- 2**: A large, hollow cylindrical component with longitudinal ribs.
- 3**: A small, cylindrical component with a central hole.
- 4**: A small, flat, circular washer or spacer.
- 5**: A small, flat, circular washer or spacer.
- 6**: A small, cylindrical component with a central hole.
- 7**: A small, cylindrical component with a central hole.
- 8**: A small, cylindrical component with a central hole.
- 9**: A small, cylindrical component with a central hole.
- LH**: Left Hand, indicating the orientation of the assembly.
- RH**: Right Hand, indicating the orientation of the assembly.

The diagram shows the relative positions and assembly sequence of these components, with the shaft (1) passing through the central hole of the large cylinder (2) and the smaller components (3, 4, 5, 6, 7, 8, 9) being inserted into the shaft.

Revision 5/19/2025